<u>'</u>
í Í
ĺ
,
;

9
₹
N
~
H
. · ·
~
Image: Control of the
#
IUMBER
Z
H
Z
MENT
5
0CT
Ξ

O = Corner monument restored.

\sim	
O	
4	
Ŋ.	
7	
7	
يخ	
땅	
NUMBER	
2	
Ľ	
MENT	
Z	
5	

	55 6		aaa		
U.S.	PUBLIC	LAND	SURVEY	MONUMENT	RECORD

Index	No.	Z-9
index	110.**	

Chala of Milanasanais		index No
State of Wisconsin ss.	History of original corner establishment:	
I	Original Government Survey in 1858 by Artemas Curtis. Dependent Res Hugh B. Crawford. East on the South side of Section 32, 79.30 chai corner is determined from the remains of original bearing trees. At set a concrete monument, 2 feet long, 6 inches in dia., 18 inches i an iron post in center, and a brass cap mkd; SC, T41N, R14E, S32, S the following bear; Y. Birch 22" N29°00'E 107 lks.(70.62 feet) Maple 12" N43°45'W 79 lks.(52.14 feet) Cedar Post 5" N3°00'W 4 lks.(2.64 feet) Found monument as described and in place, from which the following Y. Birch 25" N29°00'E 70.62 feet Maple 16" N43°45'W 52.14 feet	ns, the point for the corner point, in the ground, with 33, 1945. From which
Resident witnesses:	Cedar Post 5" N 3°00'W 2.64 feet	
Tony Tillman	Description of monument and accessories I established to perpetuate the original location	n of this corner.
SECTION 32	Dated at <u>Hiles</u> , Wis., this 1st day of October	r 19. [{]
	Signature William B. Cochrane Title Land Surveyor (County Surveyor, Registered Land Surveyor, or other duly authorized official)	Registration No. $S-1$: ereby certify that the wi

Title Land Surveyor Registration No. S-1107 and Surveyor, or other duly authorized official) rest I hereby certify that the within the harch the day of March 1987


(e) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

See drawing below.

(r) was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

Restored through acceptance of a found perpetuated location.

(gkh) was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?



William B. Cochrane (i) i,

1:1

(type or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Signature

Certificate ready for filing: 4 District Ranger

Date

Land Surveyor Scal

WILLIAM B.

COCHRANE

S-1107

HILES,

WISCONSIN