	Ì
E	Č
ler Compa	2
KC Mile	-
	1

IIS	PUBLIC	IAND	SURVEY	MONUMENT	RECORD
U.J.		LAND	30114	INICIACIAITIAI	INECOIND

		_
		7_1
Indev	No	~ ~

O = Corner monument restored.	Ву			Deputy		,
		(Register of l	·			
		(Doctor of 1	Donde)			
	ato'clock	М.				
			record on the	day	of	19
	Office of Register of I	Deeds, County	of	•••••	, I hereby ce	
	Signature.	nty Surveyor, Reg	gistered Land Surveyor	, or other duly authorized	Kegist official)	ration No. S-1107
	Simotone 1.1.00:	B P. 1	? Laue Title L	and Surveyor	Darie	ration No. S-1107
SECTION 31	Dated at Hi	1es	, Wis., this	23rd day of	December	1985
i i i						
		<del></del>				
	Spruce Steel Sign		N32 W NW	0.50 feet		en e
	Spruce	12" 7"	N88°E N32°W	37.40 feet 24.83 feet		
			<del>-</del>	_		
	Blazed and scrib	ed the foll	owing new bear	ing trees:		
	Description of monun	nent and access	sories I established	to perpetuate the orig	inal location of this	corner.
					<i>f</i>	
Tony Tillman						
Resident witnesses:						
Desired and automates						
location of this corner.			A contract of the contract of			
I established a new monument and accessories as described hereon to perpetuate the original	Monument as desc	ribed and i	n place.			
as described hereon; and that from this evidence	Description of corner	evidence found	i:			
15 East Fourth Principal Meridian,						
Township 41 , North, Range	Poplar	6"	N31°30'W	20 1ks.		
evidence of the Southwest Standard Section corner of Section 31	Poplar	5"	N21°00'E	21 1ks.	·	
certify that on the 23rd day of August 19 84, I found		S31, 1945.	From which th	e following bear;		
certify that on the 23rd day				n the ground, wit		
I William B. Cochrane , do hereby				emas Curtis. Depe Section 36, 79.48		
County of Florence	-			and Counties Dance		4- 10/5 1
State of Wisconsin } ss.	History of original co	rner establishn	ient:			


(e) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

See drawing below.

(f) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

Restored through acceptance of a found perpetuated location.

(g&h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?



male

District Ranger

WILLIAM B.
COCHRANE
S-1107
HILES,
WISCONSIN

SURVINIA

(type or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

William B. Cochrane

Certificate ready for filing:

3-9-87

Date

## Stock No. 26273

132/
NUMBER
DOCUMENT

O.O. FOREIO CAITE CONTER MONOMENT MEDONE	U.S.	PUBLIC	LÁND' SURVEY	MONUMENT	RECORD
--	------	--------	--------------	----------	--------

Index	No	Z-25
HILLEA	1 4 6 7 .	

State of Wisconsin
County of Forest ss.
I William B. Cochrane do hereby certify that on the 23rd day of August 19.84., I found evidence of the Southeast Standard Section corner of Section 36.  Township 41 North, Range 14 East Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.
Resident witnesses:
Tony Tillman
SECTION 36
1 1 1
<del> </del>
O = Corner monument restored

History of original corner establishment:
Original Government Survey in 1858 by Artemas Curtis. Dependent Resurvey in 1945 by
Hugh Crawford. East on the South side of Section 36, 79.48 chains, set a 6" diameter
concrete monument, 2 feet long, 1½ feet in the ground, with a brass cap mkd; S.C., T41N,
R14E, R15E, S36, S31, 1945. From which the following bear;

 Poplar
 5"
 N21°00'E
 21 1ks.

 Poplar
 6"
 N31°30"W
 20 1ks.

Description of corner evidence found:

Monument as described and in place.

Description of monument and accessories I established to perpetuate the original location of this corner.

Blazed and scribed the following new bearing trees;

Spruce	12"	N88°E	37.40 feet
Spruce	7''	N32°W	24.83 feet
Steel Sign	Post	NW	0.50 feet

Dated at Hiles , Wis., this 23rd day of December , 19.85

Signature William B. Cochrace Title Land Surveyor Registration No. S-1107

(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Forest , I hereby certify that the within instrument was filed in this office for record on the 11th (lay of March 19.87)

at 3:30.o'clock P. M.

(Register of Deeds)

\_\_\_\_\_Deput


(e) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or recstablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

See drawing below.

(f) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

Restored through acceptance of a found perpetuated location.

(g&h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?



Affix Land Surveyor Scal

WILLIAM B.

COCHRANE
S-1107
HILES,
WISCONSIN

SURVEYORD

SURVE

(i) William B. Cochrane

(type or print name; certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

William B. Cochrane October 8, 1980

Certificate ready for filing:

District Ranger

Date