CERTIFIED LAND CORNER RESTORATION

Index No. N-3

State	of	Wisconsin	1
County of	L	ANGLADE	2 S

I , R. W. NORDIN , do hereby certify that on the 20TH day of JUNE , 19 79, I found evidence of the NORTH QUARTER corner of SECTION 19 Township....30..., North, Range 12 EAST Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:

S. R. NORDIN

TIM WOLF

JOE HOLLRITH

T30N RIZE								
	1	1	1					
	1	I	1 -					
	<u> </u>		<u> </u>					
	1	l I	1					
	1	1.0	İ					
		1:9	<u>-</u>					
		Ì	1					
	-		<u> </u>					
	1	Ì	(
	1	1	1					
	1	*]	1					

O = Corner monument restored.

History of original corner establishment:

U. S. GOV'T. FIELD NOTES.



Description of corner evidence found:

EXCAVATED FOR CORNER IN ROADBED. FOUND REMAINS OF DECAYED WOOD AT POINT FOR CORNER, IN LINE WITH FENCE TO NORTH.


Description of monument and accessories I established to perpetuate the original location of this corner.

SET STANDARD LANGLADE COUNTY BRASS-CAPPED IRON PIPE FOR CORNER. (SEE REVERSE SIDE FOR TIES)

Dated at SHAWANO	Wis., this 25TH	day of	JUNE	, 197.9
Signature (County Surveyor, Registered	Title LAND	SURVEYORther duly authorized of	Registrat ficial)	ion No. S-791
Office of Register of Deeds, County of	rd on the	day o	, I hereby certif	fy that the within 19
(Register of Deeds)				

...Deputy

43012180020



DENOTES I" IRON PIPE SET.
BEARINGS ARE MAGNETIC.

'A' = N.02° - 16' W. 56.68'

'B' = S. 20° - 36' E. 60.46'

'C' = \$.45°-54'W. 70.55'

SECTION 19