
County of		Viscon Lade			s.
-	-				1 .
certify tha	it on the	, 1	5 th	, dc	nerebi da
			, 19.	80 ,	I found
evidence o	f theV	1.1/8 line c	f Sec	1	
corner oi Township	32			North	. Range
11		, Fourt	h Princ	ipal M	eridian
as describe Lestablish		15			
ıs describe					
ocation of	this cor	ner.			
Resident w	vitnesses	•			
rediacire vi	, refreeded	•			
·································					·
	·····				
		!		T	

	 -			 	
	 			1 1 1	

CERTIFIED LAND CORNER RESTORATION

History of original corner establishment:

N one



Description of corner evidence found:

Set monument at 1308' easterly of SW 1 using information on a Langlade Co. deed v. 152, p 536. The deed shows an angle point that most likely is the sec. corner.

Description of monument and accessories I established to perpetuate the original location of this corner.

	.08°E 1 <u>4</u> 8	.23 . Aspen 9"	
Rocky Rd.		assumed 1/8 pipe is \$78°E	E 12.19'
546 N		188.621 D. P. Pole	
Basswood 18"	×		
Data Lat	Boulder Jos	t Wia thia	151

Set 1%" axle shaft in the north edge of the travelled way of Rocky Rd. approx. west of fence line.

5	Dans I dans	T - 1	* * * * *		4	LL		c	**			•
Dated at	Doulder	UCTe	, W1s	, this		ַבַּבַּ	.day	otto	.December		19	Q
		17		•		-	•			•		

Signature Marin E Seymour Title Land Surveyor Registration No. S=1412 (County Surveyor, Registered Land Surveyor, or other duly authorized official)

(Register of Deeds)

By......Deputy