

CERTIFIED LAND CORNER RESTORATION

32-12  
Index No. B-17

State of Wisconsin }  
County of Langlade } ss.

I Raymond J. Hallsy, do hereby certify that on the 6th day of June, 19 71, I found evidence of the N 1/16 corner of Section 3 & 2 Township 32, North, Range 12E, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:

.....  
.....  
.....

History of original corner establishment:

Corner set in the 1930 resurvey.

Description of corner evidence found:

Found old wood stake standing, marked S2 S3 N1/16, rock mound.


Description of monument and accessories I established to perpetuate the original location of this corner.

Set 2" pipe with brass cap, rock mound.

BT's to corner  
16" Hemlock N31E 34 Ft. 2 inches  
10 Elm S10E 16 Ft. 7 inches  
BT's faced at base of tree and scribed BT.



FORM 985 H. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.

Dated at Antigo, Wis., this 6th day of June, 19 71

Signature R. J. Hallsy Title Reg. Land Surveyor Registration No. 185  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of \_\_\_\_\_, I hereby certify that the within instrument was filed in this office for record on the \_\_\_\_\_ day of \_\_\_\_\_, 19 \_\_\_\_\_ at \_\_\_\_\_ o'clock \_\_\_\_\_ M.

(Register of Deeds)

By \_\_\_\_\_ Deputy