

CERTIFIED LAND CORNER RESTORATION

Index No. E-9

32-12

State of Wisconsin }
 County of Langlade } ss.

I Raymond J. Hallisy, do hereby certify that on the 25th day of MARCH, 19 78, I found evidence of the W.C. corner of 4, 5, 8, 9 Township 32, North, Range 12 EAST, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:


.....

History of original corner establishment:

Corner Established in 1939 Resurvey

Description of corner evidence found:

4 inch Iron Pipe With Brass CAP
1/4 inch PIPE By corner




Description of monument and accessories I established to perpetuate the original location of this corner.

ELM 8" S20°E 47 FT 10 INCHS
ASPEN 5" S46°E 27 FT 2 INCHS
CHERRY 6" S80°E 36 FT 9 INCHS

FORM 985 H. C. MILLER CO., MILWAUKEE

T32N-R12E



○ = Corner monument restored.

Dated at Antigo, Wis., this 25th day of MARCH, 19 78.

Signature Raymond J. Hallisy Title Registered Land Surveyor Registration No. S-685
 (County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19..... at..... o'clock..... M.

.....
 (Register of Deeds)

By..... Deputy