O = Corner monument restored.

CERTIFIED LAND CORNER RESTORATION

32-12 Index No. (- 9

History of original corner establishment:

NEVEMBER 15, 1939
RESURVEY

Description of corner evidence found:

4" IRON PIPE WITH BRASS CAP W.C. SOLKS WEST

Description of monument and accessories I established to perpetuate the original location of this corner.

RESET SAME PIPE 100 LISS WEST OF CORNER