

CERTIFIED LAND CORNER RESTORATION

Index No. G-5
32-12

State of Wisconsin }
County of Langlade } ss.

I Raymond J. Hallisy, do hereby certify that on the 2nd day of December, 1977, I found evidence of the 1/4 corner of 7 & 8 Township 32, North, Range 12E, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

History of original corner establishment:

Corner set in the 1930 resurvey.

Description of corner evidence found:

4" iron pipe with brass cap


Resident witnesses:

.....
.....
.....


Description of monument and accessories I established to perpetuate the original location of this corner.

NEW BT'S

9" Cherry N18E 36' 9"
10" Cherry N62E 24' 6"
4" Elm S46E 11' 1"



FORM 985 R. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.

Dated at Antigo, Wis., this 2nd day of December, 1977

Signature Raymond J. Hallisy Title Land Surveyor Registration No. 5685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

.....
(Register of Deeds)

By.....Deputy