

CERTIFIED LAND CORNER RESTORATION

Index No. J-21

32-12

State of Wisconsin }  
County of Lanaiade } ss.


I, Raymond J. Hallisy, do hereby certify that on the 29th day of April, 1978, I found evidence of the Section corner of 11, 12, 13, 14 Township 32, North, Range 12 EAST, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

History of original corner establishment:

Corner Established in 1939 Resurvey

Description of corner evidence found:

4 inch Iron Pipe With Brass cap




Resident witnesses:

.....  
.....  
.....

Description of monument and accessories I established to perpetuate the original location of this corner.

New B.T.s  
Aspen 2" N40°W 12 FT. 3 inchs  
cherry 6" S42°W 47 FT. 10 inchs  
cherry 7" N63°W 56 FT. 3 inchs



○ = Corner monument restored.

Dated at Antigo, Wis., this 29th day of April, 1978.

Signature Raymond J. Hallisy Title Registered Land Surveyor Registration No. 5-685  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of \_\_\_\_\_, I hereby certify that the within instrument was filed in this office for record on the \_\_\_\_\_ day of \_\_\_\_\_, 19\_\_\_\_ at \_\_\_\_\_ o'clock \_\_\_\_\_ M.

.....  
(Register of Deeds)

By \_\_\_\_\_ Deputy