

CERTIFIED LAND CORNER RESTORATION

Index No. G-21

State of Wisconsin }  
County of Kanglade } ss.


History of original corner establishment:

Corner Established in 1939 Resurvey

I, Raymond J. Hallisy, do hereby certify that on the 29th day of April, 1978, I found evidence of the West 1/4 corner of Section 12 Township 32, North, Range 12 EAST, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Description of corner evidence found:

4 inch Iron Pipe With Brass CAP



Resident witnesses:


Description of monument and accessories I established to perpetuate the original location of this corner.

New B.T.s

- Cherry 9" S51°E 12 FT 3 inches
- Aspen 7" S88°E 25 FT 3 inches
- Aspen 4" S19°E 6 FT 5 inches

FORM 985 H. C. MILLER CO., MILWAUKEE

T 32 N R 12 E



○ = Corner monument restored.

Dated at Antigo, Wis., this 29th day of April, 1978.

Signature Raymond J. Hallisy Title Registered Land Surveyor Registration No. S-685  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of \_\_\_\_\_, I hereby certify that the within instrument was filed in this office for record on the \_\_\_\_\_ day of \_\_\_\_\_, 19\_\_\_\_ at \_\_\_\_\_ o'clock \_\_\_\_\_ M.

(Register of Deeds)

By \_\_\_\_\_ Deputy