

CERTIFIED LAND CORNER RESTORATION

Index No. L-21

State of Wisconsin }
County of Lanai } ss.


History of original corner establishment:

corner established in 1939 Resurvey

I, Raymond J. Hallisy, do hereby certify that on the 29th day of April, 1978, I found evidence of the West 1/4 corner of Section 13 Township 32, North, Range 12 East, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Description of corner evidence found:

4 inch Iron Pipe with Brass Cap
Rock mound




Resident witnesses:

Description of monument and accessories I established to perpetuate the original location of this corner.

New B.T.s
Basswood 7" N6E 9 FT. 2 inches
Hard Maple 8" N35E 22 FT. 3 inches
ELM 7" S19E 10 FT

FORM 985 H. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.

Dated at Antigo, Wis., this 29th day of April, 1978.

Signature Raymond J. Hallisy Title Registered Land Surveyor Registration No. S-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy