State of Wisconsin  County of Latilade ss.					
IRaymend J. Hallisy, do hereby certify that on the					
Resident witnesses:					
Section Section  Section Section  Section Section					

O = Corner monument restored.

## CERTIFIED LAND CORNER RESTORATION

Index No. 28-25

History of original corner establishment:

32-12

Govt. distance to swamp 11.00 chains West.

Description of corner evidence found:

Measured North from 1/4 to 1 & 6 T31W R12 & R13F, 39.46 Chains, Hutchinson's distance. Found his vine stump PT's

36" N6½W 55.5 Links 24" S74F 80.75 Links

Description of monument and accessories I established to perpetuate the original location of this corner.

Set New	2" pipe with br BT's	es cap fro	m (ld PT's	132 N
6н	Palsom	N79W	13.1 Ft.	36131
12"	Elm	MSTAM	6.1 Ft.	(RILE 36 131 RISE)
8"	Cherry	S39E	24.2 Ft.	131 N
Ļ'n	Hard Maple	532W	21.6 Ft.	

(Register of Deeds)

By......Deputy