

U.S. PUBLIC LAND SURVEY MONUMENT RECORD


Note: This form is intended and designed to fulfill all requirements of Wisconsin Administrative Code, Chapter A-E 5.02, U.S. Public Land Survey Monument Record (3) (a) (b) (c) (d) (e) (f) (g) (h) (i). An additional sheet may be added if necessary to conform with said requirements.

(a) Corner location: Township 32 North

Range 14 East ~~14~~

Town/County ~~City~~ Wolf River

County Langlade




Section 32

(b) (f) (g) (h) Description of monument found at this corner and if it was accepted and if it was accepted, state all evidence (material, testimonial, occupational, plats, records, other monuments) used as a basis for accepting. If not accepted or if nothing was found, state evidence used as basis for establishing location. If reestablished through lost corner proportionate methods, indicate all monuments, distances and directions used to establish.

Could not find wood post, as was shown on 1972 D.O.T. Highway plan, so I set i.p. at bearing + distance from tag on tree. The point fell exactly on G of stated out plan as I did it. (It matched the plan) Point is just north of meandering newer fence.

(c) (d) (e) Plan view of corner with ties to at least 4 witness monuments. If in disagreement with previously established corner, show the distances between the two corners and also indicate the ties to the disputed corner.



*Alum. tag on tree, 1962 by Deleson Koch
Cor. is N 50° W, 17 lks.*

(i) I, Marvin E. Seymour
(type or print name) certify that the corner location on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Marvin E. Seymour May 31, 1988
Signature Date

