

CERTIFIED LAND CORNER RESTORATION

Index No. E-18

State of Wisconsin }  
County of Lanai } ss.

I, Raymond Hallisy, do hereby certify that on the 9th day of May, 1987, I found evidence of the W 1/16 corner of Set section 2 + 11 Township \_\_\_\_\_, North, Range \_\_\_\_\_, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:

.....  
.....  
.....

History of original corner establishment:  
Corner set in 1930, Resurvey

Description of corner evidence found:  
Squared Cedar post scribed + standing + Rock mound.

Description of monument and accessories I established to perpetuate the original location of this corner.


Set 1 1/2" I. pipe with Aluminum cap  
Rockmound Around corner



New BT's  
Aspen 10" N39° W 30' 10"  
Balsam 8" S73° E 33' 9"

FORM 985 H. C. MILLER CO., MILWAUKEE

T 33 N R 11 E



○ = Corner monument restored.

Dated at Antigo, Wis., this 9th day of May, 1987  
Signature Raymond Hallisy Title Land Surveyor Registration No. 5-685  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of \_\_\_\_\_, I hereby certify that the within instrument was filed in this office for record on the \_\_\_\_\_ day of \_\_\_\_\_, 19\_\_\_\_ at \_\_\_\_\_ o'clock \_\_\_\_\_ M.

(Register of Deeds)

By \_\_\_\_\_ Deputy