

CERTIFIED LAND CORNER RESTORATION

Index No. E-17

State of Wisconsin }  
County of Langlade } ss.

History of original corner establishment:

Corner set in the 1930 resurvey.

I Raymond J. Hallisy, do hereby certify that on the 6th day of May, 1979, I found evidence of the Section corner of 2, 3, 10, & 11 Township 33, North, Range 11E, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Description of corner evidence found:

4" pipe with brass cap.


Resident witnesses:

.....  
.....  
.....


Description of monument and accessories I established to perpetuate the original location of this corner.

New BT's

10" Basswood S36W 17' 5"  
5" Cherry N87E 35' 3"  
12" Basswood N65E 48'  
4" Hard Maple N55W 31' 6"



Rock mound



○ = Corner monument restored.

Dated at Antigo, Wis., this 6th day of May, 1979.

Signature Raymond J. Hallisy Title Reg. Surveyor Registration No. S-685  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of....., I hereby certify that the within instrument was filed in this office for record on the.....day of....., 19..... at.....o'clock..... M.

.....  
(Register of Deeds)

By.....Deputy

FORM 985 H. C. MILLER CO. MILWAUKEE