

CERTIFIED LAND CORNER RESTORATION

Index No. C-17

State of Wisconsin }
County of Lanola } ss.

History of original corner establishment:

Corner set in the 1930 resurvey.

I Raymond J. Hallisy, do hereby certify that on the 6th day of May, 1979, I found evidence of the 1/4 corner of Section 2 & 3 Township 33, North, Range 11E, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Description of corner evidence found:

4" pipe with brass cap on the South bank of the Hunting River.

Resident witnesses:


.....
.....
.....

Description of monument and accessories I established to perpetuate the original location of this corner.


New BT's

11" Cherry S3W 48' 5"
16" Tamarack S45W 45' 5"
8" Cherry S87W 29'

Rock mound



FORM 985 H. C. MILLER CO. - MILWAUKEE



O = Corner monument restored.

Dated at Antigo, Wis., this 6th day of May, 1979.

Signature Raymond J. Hallisy Title Reg. Surveyor Registration No. S-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19..... at..... o'clock..... M.

.....
(Register of Deeds)

By..... Deputy