

CERTIFIED LAND CORNER RESTORATION

Index No. E-11

State of Wisconsin }
County of LANGLADE } ss.

History of original corner establishment:

CORNER SET IN 1936 RESURVEY

I RAYMOND J. HALLISY, do hereby certify that on the 28th day of AUGUST, 1976, I found evidence of the 1/4 corner of Section 4 Township 33, North, Range 11E, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Description of corner evidence found:



4" IRON PIPE WITH BRASS CAP

Resident witnesses:

.....
.....
.....

Description of monument and accessories I established to perpetuate the original location of this corner.

NEW B.T.S
Mh 10" S 70° E 21.4 Feet
W. ASH clump S 18° E 3.4 Feet



○ = Corner monument restored.

Dated at Appt 190, Wis., this 28th day of August, 1976

Signature Raymond J. Hallisy Title Registered Land Surveyor Registration No. 5685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19..... at..... o'clock..... M.

.....
(Register of Deeds)

By..... Deputy