

CERTIFIED LAND CORNER RESTORATION

88-11

Index No. E-10

State of Wisconsin }
County of Langlade } ss.

History of original corner establishment:

Corner set in the 1930 resurvey

I, Raymond J. Hallisy, do hereby certify that on the 15th day of November, 1969, I found evidence of the W 1/16 corner of Section 9 Township 33, North, Range 11E, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Description of corner evidence found:


Found old stake down, point intact, rock mound.
Stake marked 4 9 1/8

Resident witnesses:


.....
.....
.....

Description of monument and accessories I established to perpetuate the original location of this corner.

Set 2" pipe with brass cap, rock mound.
B.T.'s to corner
Yellow Birch 7" S23E 28 Lks.
Yellow Birch 8" S11W 29 Lks.
B.T.'s faced at base of tree and marked BT



FORM 985 H. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.

Dated at Antigo, Wis., this 15th day of November, 1969

Signature Raymond J. Hallisy Title Reg. Land Surveyor Registration No. S-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of....., I hereby certify that the within instrument was filed in this office for record on the.....day of....., 19..... at.....o'clock..... M.

.....
(Register of Deeds)

By.....Deputy