

CERTIFIED LAND CORNER RESTORATION

Index No. J-13

33

State of Wisconsin }
County of Lanlade } ss.

I Raymond J. Hallisy, do hereby certify that on the 29th day of April, 1978, I found evidence of the section corner of 9, 10, 15, 16 Township 33, North, Range 11 E, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:


.....
.....
.....

History of original corner establishment:

Established in 1936 RESURVOY

Description of corner evidence found:

4 inch Iron PIPE With BRASS CAP
OLD B.T. HARD MAPLE 26" N63°E 35 FT. 6 inches




Description of monument and accessories I established to perpetuate the original location of this corner.

NEW B.T.S
YELLOW Birch 4 inch S82°W 7 FT. 4 inches
HARD MAPLE 10 inch N17°W 29 FT. 10 inches
HARD MAPLE 5 inch S3°W 5 FT. 4 inches
Cherry 11 inch N11°E 10 FT. 7 inches

FORM 985 H. C. MILLER CO., MILWAUKEE

T 33 N R 11 E



○ = Corner monument restored.

Dated at Antigo, Wis., this 29th day of April, 1978.

Signature Raymond J. Hallisy Title Registered Land Surveyor Registration No: 5-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy