

CERTIFIED LAND CORNER RESTORATION

83-11
Index No. F-13


State of Wisconsin }
County of Langlade } ss.

I Raymond J. Hallisy, do hereby
certify that on the 24th day
of May, 19 70, I found
evidence of the N 1/16
corner of Section 9
Township 33, North, Range
11E, Fourth, Principal Meridian,
as described hereon; and that from this evidence
I established a new monument and accessories
as described hereon to perpetuate the original
location of this corner.

Resident witnesses:

J. Weir
J. Krylo

FORM 985 H. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.

History of original corner establishment:

Corner set in the 1930 resurvey.

Description of corner evidence found:

Found old stake down point intact, rock mound, marks not plain.

Description of monument and accessories I established to perpetuate the original location of this corner.

Set 2" pipe with brass cap, rock mound.

New B.T.'s

Aspen 8" N7E 11 Ft. 4 inches

Aspen 5" S29E 5 Ft. 5 inches

B.T.'s faced at base of tree and scribed BT.



Dated at Antigo, Wis., this 24th day of May, 19 70

Signature Raymond J. Hallisy Title Reg. Land Surveyor Registration No. S-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within
instrument was filed in this office for record on the _____ day of _____, 19____
at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy