

CERTIFIED LAND CORNER RESTORATION

Index No. J-17  
33-11

State of Wisconsin }  
County of Langlade } ss.

I, Raymond J. Hallisy, do hereby certify that on the 5th day of May, 1979, I found evidence of the Section corner of 10, 11, 14, & 15 Township 33, North, Range 11E, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

History of original corner establishment:

Corner set in the 1930 resurvey.

Description of corner evidence found:

4" pipe with brass cap.



Resident witnesses:

.....  
.....  
.....

Description of monument and accessories I established to perpetuate the original location of this corner.

New BT's

12"	Spruce	N27E	10' 6"
5"	Twin Spruce	N10W	8' 6"
11"	Spruce	N55E	13' 9"
5"	Spruce	N79E	2' 1"



○ = Corner monument restored.

Dated at Antigo, Wis., this 5th day of May, 1979

Signature Raymond J. Hallisy Title Reg. Surveyor Registration No. S-685  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of Langlade, I hereby certify that the within instrument was filed in this office for record on the 5th day of May, 1979 at 10:11 o'clock AM.

.....  
(Register of Deeds)

By..... Deputy