

CERTIFIED LAND CORNER RESTORATION

Index No. J-15

State of Wisconsin }
County of Langlade } ss.


History of original corner establishment:

Established in 1936 Resurvey

I Raymond J. Hallisy, do hereby certify that on the 29th day of April, 1978, I found evidence of the South 1/4 corner of Section 10 Township 33, North, Range 11E, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Description of corner evidence found:

4 inch Iron pipe with Brass cap



Resident witnesses:


.....
.....
.....

Description of monument and accessories I established to perpetuate the original location of this corner.

- Hard maple 7 inch N58°W 25 FT. 5 inches
- Basswood 10 inch S64°W 13 FT. 7 inches
- Hard maple 8 inch S50E 28 FT 2 inches

FORM 985 H. C. MILLER CO., MILWAUKEE

T 33 N R 11 E



○ = Corner monument restored.

Dated at Antigo, Wis., this 29th day of April, 1978.

Signature Raymond J. Hallisy Title Registered Land Surveyor Registration No. S-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of, I hereby certify that the within instrument was filed in this office for record on the day of, 19..... at o'clock M.

.....
(Register of Deeds)

By..... Deputy