

CERTIFIED LAND CORNER RESTORATION

Index No. H-17

State of Wisconsin }  
County of Lantern } ss.

History of original corner establishment:

Corner set in the 1930 resurvey.

I Raymond J. Hallisy, do hereby certify that on the 8th day of May, 1979, I found evidence of the S 1/16 corner of Section 10 & 11 Township 33, North, Range 11E, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Description of corner evidence found:

Wood post down, point intact, marked 10, 11, 1/8, Rock mound


Resident witnesses:

.....  
.....  
.....


Description of monument and accessories I established to perpetuate the original location of this corner.

Set 1 1/2" pipe with brass cap  
New BT's

6" Hard Maple S6E 2' 2"  
6" Hard Maple N33W 14' 5"  
10" Hard Maple S79E 20' 6"



Rock Mound



○ = Corner monument restored.

Dated at Antigo, Wis., this 8th day of May, 1979

Signature Raymond J. Hallisy Title Reg. Surveyor Registration No. S-685  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of \_\_\_\_\_, I hereby certify that the within instrument was filed in this office for record on the \_\_\_\_\_ day of \_\_\_\_\_, 19\_\_\_\_ at \_\_\_\_\_ o'clock \_\_\_\_\_ M.

.....  
(Register of Deeds)

By \_\_\_\_\_ Deputy