

CERTIFIED LAND CORNER RESTORATION

Index No. **G-17**

33-11

State of Wisconsin }
County of Langlade } ss.

I Raymond J. Hallisy, do hereby certify that on the 5th day of May, 19 79, I found evidence of the 1/4 corner of Section 10 & 11 Township 33, North, Range 11E, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

History of original corner establishment:

Corner set in the 1930 resurvey.

Description of corner evidence found:

4" pipe with brass cap
Rock with X S54W 17'2"

Resident witnesses:



.....
.....
.....

Description of monument and accessories I established to perpetuate the original location of this corner.

New BT's

6" Spruce N29E ~~28~~ 9' 7"
6" Spruce N36W 15' 5"
10" Spruce S22W 31' 1"

Rock mound



○ = Corner monument restored.

Dated at Antigo, Wis., this 5th day of May, 19 79.

Signature Raymond J. Hallisy Title Reg. Surveyor Registration No. S-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19 _____ at _____ o'clock _____ M.

.....
(Register of Deeds)

By _____ Deputy

FORM 985 H. C. MILLER CO., MILWAUKEE