

CERTIFIED LAND CORNER RESTORATION

33-11
Index No. P-15

State of Wisconsin }
County of Langlade } ss.

History of original corner establishment:

I Christy T. Hauge, do hereby
certify that on the ninth day
of July, 19 62, I found
evidence of the center marker
corner of Section 22
Township 33, North, Range
11 East, Fourth Principal Meridian,
as described hereon; and that from this evidence
I established a new monument and accessories
as described hereon to perpetuate the original
location of this corner.



Description of corner evidence found:

Found old squared tamarack stake. Point was broken off in
the ground. No B.T. trees were found.

Resident witnesses:

Description of monument and accessories I established to perpetuate the original location of this corner.

Dug old point out and reset pipe in same hole. Set brass
cap welded into a 4 foot section of 1 1/4" pipe. Pipe extended
2 feet above ground and is mounted with cement around it.
New B.T. A. Elm 17.2" S 52° E 50' (compass set at 0°)
New B.T. A. Elm 12.6" N 60° E 54' (compass set at 0°)
Elm growing in clump of 4.



○ = Corner monument restored.

Dated at Antigo, Wis., this 9th day of July, 19 62

Signature Christy T. Hauge Title Forester, W. C. D. Registration No. _____
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within
instrument was filed in this office for record on the _____ day of _____, 19 _____
at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy