

CERTIFIED LAND CORNER RESTORATION

Index No. R-21

State of Wisconsin }
County of Langlade } ss.

I Raymond J. Hallisy, do hereby certify that on the 28th day of August, 1976, I found evidence of the section corner of 23, 24, 25, 26 Township 33, North, Range 11 E, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.



History of original corner establishment:
ESTABLISHED August 25, 1936
IN RESURVEY

Description of corner evidence found:
4" IRON PIPE WITH BRASS CAP

Resident witnesses:
.....
.....
.....

Description of monument and accessories I established to perpetuate the original location of this corner.

NEW B.T.S.
Hard Maple 8" S84E 48.2 Feet
Hard maple clump N20W 44.7 Feet



○ = Corner monument restored.

Dated at Antigo, Wis., this 28th day of August, 1976.

Signature Raymond J. Hallisy Title Registered Land Surveyor Registration No. 5685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of....., I hereby certify that the within instrument was filed in this office for record on the.....day of....., 19..... at.....o'clock..... M.

.....
(Register of Deeds)

By.....Deputy

FORM 985 H. C. MILLER CO., MILWAUKEE