

CERTIFIED LAND CORNER RESTORATION

33-11

Index No. V-22-23

State of Wisconsin }
County of Langlade } ss.

History of original corner establishment:

Corner set in the 1930 resurvey.

I, Raymond J. Hallisy, do hereby certify that on the 24th day of May, 1970, I found evidence of the MC corner of Section 25 & 36 Township 33, North, Range 11E, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Description of corner evidence found:

MC was removed and witnessed when the parking lot on Pence Lake was developed.

Resident witnesses:



J. Kryko
J. Weix

Description of monument and accessories I established to perpetuate the original location of this corner.

4th Brass cap in cement was returned to original position after development New B.T.

White Pine 24" NW 76 Ft.

B.T. faced at base of tree and scribed BT.



Dated at Antigo, Wis., this 24th day of May, 1970

Signature Raymond J. Hallisy Title Reg. Land Surveyor Registration No. S-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of Langlade, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy

○ = Corner monument restored.