

CERTIFIED LAND CORNER RESTORATION

Index No. V-19

33-11

State of Wisconsin }  
County of Lanlade } ss.

I Raymond J. Hallisy, do hereby certify that on the 8<sup>th</sup> day of April, 19 78, I found evidence of the South 1/4 corner of SECTION 26 Township 33, North, Range 11 E, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:


.....  
.....  
.....

History of original corner establishment:

Corner Established in 1936 Resurvey

Description of corner evidence found:

Found 4 inch IRON PIPE WITH BRASS CAP  
FENCE EAST AND SOUTH




Description of monument and accessories I established to perpetuate the original location of this corner.

New B.T.s

HARD MAPLE 22" N53°W 39 FT. 3 INCHS  
WHITE SPRUCE 10" N7°W 42 FT. 3 INCHS

FORM 985 M. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.

Dated at Ant 190, Wis., this 8<sup>th</sup> day of April, 19 78.

Signature Raymond J. Hallisy Title Registered Land Surveyor Registration No. 5685  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19..... at..... o'clock..... M.

.....  
(Register of Deeds)

By..... Deputy