

CERTIFIED LAND CORNER RESTORATION

33-11 Index No. Y-13


State of Wisconsin }
County of Laclede } ss.

I, Raymond J. Hallisy, do hereby certify that on the 12th day of June, 1971, I found evidence of the S 1/16 corner of Section 33 & 34 Township 33, North, Range 11E, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:

.....
.....
.....

FORM 985 M. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.

History of original corner establishment:

Corner set in ~~KMM~~ the 1930 resurvey.

Description of corner evidence found:

Found old wood stake standing, marked 1/8 33 34, rock mound.

Description of monument and accessories I established to perpetuate the original location of this corner

Set 2" pipe with brass cap, rock mound.

BT's to corner
6" Hard Maple S74W 27 Feet 3 inches
5" Balsam S72E 26 Feet 9 inches
BT's faced at base of tree and scribed BT.



Dated at Antigo, Wis., this 12th day of June, 1971

Signature: R. J. Hallisy Title: Reg. Land Surveyor Registration No. 685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

.....
(Register of Deeds)

By..... Deputy