

CERTIFIED LAND CORNER RESTORATION

33-11
Index No. X-23

State of Wisconsin }
County of Langlade } ss.

History of original corner establishment:

I, Raymond J. Hallisy, do hereby certify that on the 22nd day of August, 19 70, I found evidence of the Center 1/4 corner of Section 36 Township 33, North, Range 11E, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Corner set by Dorr

Description of corner evidence found:

Found old Well Point

Resident witnesses:


.....
.....
.....

Description of monument and accessories I established to perpetuate the original location of this corner.

Set 2" pipe with brass cap in cement monument 4" by 2 Ft.

~~XXXXXXXXXX~~

No B.T.'s Road to west and south



○ = Corner monument restored.

Dated at Antigo, Wis., this 22nd day of August, 19 70

Signature Raymond J. Hallisy Title Reg. Land Surveyor Registration No. S-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19 _____ at _____ o'clock _____ M.

.....
(Register of Deeds)

By _____ Deputy

FORM 985 H. C. MILLER CO., MILWAUKEE