


4331213 2000

U.S. PUBLIC LAND SURVEY MONUMENT RECORD

Note: This form is intended and designed to fulfill all requirements of Wisconsin Administrative Code, Chapter A-2 7.08 U.S. Public Land Survey Monument Record (3) (a) (b) (c) (d) (e) (f) (g) (h) (i). An additional sheet may be added if necessary to conform with said requirements.



a) Corner Location:

1/4 Corner of Sections 13 & 18
Township 33 North, Range 12 & 13 East
Town of Langlade,
Langlade County, Wisconsin

Langlade County Coordinates:

Datum: NAD 83 2011
N: 414038.95
E: 678490.64

b) History of Original Corner establishment:

Original Surveyor: A. Millard
Date of Survey: August, 1857

Original Accessories:

Hemlock 15" S 75° W, 30 lks.
Hemlock 24" N 70° W, 28 lks.

(b) (f) (g) (h) Description of monument found at this corner and if it was accepted, state all evidence (material, testimonial, occupational, plats, records, other monuments) used as a basis for accepting. If not accepted or if nothing was found, state evidence used as basis for establishing location. If re-established through lost corner proportionate methods, indicate all monuments, distances and directions used to establish. Indicate type of monument and sign post found or set.


1976 - Owens Illinois shows "IP By others"

1982 - R. Hallisy finds a 1" Iron Pipe and replaces it with 2" Aluminum Monument and references it:
10" Cherry S 8° E, 13.4'; 8" Cherry S 40° W, 18.9'; 7" Balsam N 70° E, 2.9'; 8" Cherry S 80° E, 19.6'

2025 - I find the Aluminum Mon. All references are gone. I referenced as shown.

(c) (d) (e) Plan view of corner with ties to at least 4 witness monuments. If in disagreement with previously established corner, show the distances between the two corners and also indicate the ties to the disputed.

Distances are to a survey nail in the side of the tree.



(i) I Charles L. Oleinik, Professional Land Surveyor No: S-2439-8, hereby certify that the corner location on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Charles L. Oleinik 10-1-25

Date

Bearings are Magnetic with a hand-held compass
No Scale



Index No. L-25

CERTIFIED LAND CORNER RESTORATION

Index No. L-25

State of Wisconsin }
County of Langlade } ss.

History of original corner establishment:

I Raymond J. Hallisy, do hereby
certify that on the 9th day
of January, 1982, I found
evidence of the 1/4
corner of Section 13 & 18
Township 33, North, Range
12E & 13E, Fourth Principal Meridian,
as described hereon; and that from this evidence
I established a new monument and accessories
as described hereon to perpetuate the original
location of this corner.

Description of corner evidence found:

1" iron pipe


Resident witnesses:

Description of monument and accessories I established to perpetuate the original location of this corner.

Set 2" Aluminum pipe with cap.

New BT's

10"	Cherry	S8E	13.4'
8"	"	S40W	18.9'
7"	Balsam	N70E	2.9'
8"	Cherry	S80E	19.6'



○ = Corner monument restored.

Dated at Antigo, Wis., this 9th day of January, 1982.

Signature Raymond J. Hallisy Title Land Surveyor Registration No. S-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within
instrument was filed in this office for record on the _____ day of _____, 19____
at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy