


4331318 2000

U.S. PUBLIC LAND SURVEY MONUMENT RECORD

Note: This form is intended and designed to fulfill all requirements of Wisconsin Administrative Code, Chapter A-E 7.08 U.S. Public Land Survey Monument Record (3) (a) (b) (c) (d) (e) (f) (g) (h) (i). An additional sheet may be added if necessary to conform with said requirements.



a) Corner Location:

1/4 Corner of Sections 17 & 18
Township 33 North, Range 13 East
Town of Langlade,
Langlade County, Wisconsin

Langlade County Coordinates:

Datum: NAD 83 2011
N: 413765.91
E: 683801.95

b) History of Original Corner establishment:

Original Accessories:

S. Maple 15" S 66 E, 75 lks.
S. Maple 8" N 66 W, 20 lks.

Original Surveyor: J. Nolin
Date of Survey: May, 1865

(b) (f) (g) (h) Description of monument found at this corner and if it was accepted, state all evidence (material, testimonial, occupational, plats, records, other monuments) used as a basis for accepting. If not accepted or if nothing was found, state evidence used as basis for establishing location. If re-established through lost corner proportionate methods, indicate all monuments, distances and directions used to establish. Indicate type of monument and sign post found or set.

1869 - Owens Illinois perpetuates corner with a 1 1/4" Iron Pipe.


1930 - W. Kelly finds the 1 1/4" Iron Pipe and replaces it with a 2 1/2" Aluminum Monument.

1991 - J. Fronsoe finds the 2 1/2" Aluminum Monument and references it: 7" Maple N 51° W, 24.4';
15" Maple N 13° E, 7'; Yellow Birch S 10° W, 2.8'; 8" Elm S 82° E, 12.2'

2025 - I find the Aluminum Mon. All references are gone except the yellow birch, S 10 W, 2.8', which is now dead.
I referenced as shown.


(c) (d) (e) Plan view of corner with ties to at least 4 witness monuments. If in disagreement with previously established corner, show the distances between the two corners and also indicate the ties to the disputed.

Distances are to a survey nail in the side of the tree.



(i) I Charles L. Oleinik, Professional Land Surveyor No: S-2439-8, hereby certify that the corner location on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Charles L. Oleinik
Date: 10-1-25



Bearings are Magnetic with a hand-held compass
No Scale

U.S. PUBLIC LAND SURVEY MONUMENT RECORD

(As Required By s. A-E 5.02, WI Adm. Code)

History of original corner establishment and subsequent restorations and description of any record, monument, occupational, testimonial or other evidence considered:

In 1865, J. Nowlin, set post and established 2 B.T.S; a Sugar 15" S.66°E. 75 lks. and a Sugar 8" N.66°W. 20 lks.

No further record evidence was found.

In 1991, I found a 2½" alum. post with cap set by W. Kelly in 1990; found 4" sq. cedar post next to alum. post; found large stump hole brng. N.66°W. 13.0' and another brng. S.70°E. 49.5' these check well with original B.T.S.


Corner was: (Check All That Apply)

- ☐ Restored through acceptance of an obliterated evidence location
- ☒ Restored through acceptance of a found perpetuated location
- ☐ Considered a lost corner and reestablished through lost corner proportionate methods (include a plan view drawing showing distances and directions to other Public Land Survey Corners used for proportioning and determining the corner location)
- ☐ Restored or reestablished in a location that differs from a previous restoration or reestablishment (include a plan view drawing and indicate what was set and/or found)



Describe the monument and accessories used to perpetuate the location of this corner. (include a plan view drawing and indicate what was set and/or found)

I accept the 2½" alum. post as best remaining evidence of corner and reference as shown.

The W. ¼
corner of Section 17,
T. 33 N., R. 13 E.,
Fourth Principal Meridian,



● = Location of Corner



I, James J. Fronsoe

S-1381

(type or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Signature James J. Fronsoe Date 8/16/91

Index No. L-5


U. S. PUBLIC LAND SURVEY MONUMENT RECORD

INSTRUCTIONS:

This record shall show the location of the corner and shall include all of the following nine elements (a through i).

- (a) Identify the corner by reference to the U.S. public land survey system.
O = Corner monument restored.


ORIG. COR. ESTABLISHED BY
J. Nowlin, MAY 1865
COR. PERPETUATED BY OWENS-ILLINOIS
IN 1969




- (b) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

FOUND 4x4 SCRIBED CEDAR POST & 1 1/4" IRON PIPE ALONG
SIDE. REPLACED IRON PIPE WITH 3" AL MONUMENT FOR CORNER.

- (c) In the plan view drawing below, provide reference ties to at least 4 witness monuments, or, if the location is within a municipality, to at least 2 witness monuments. (Witness monuments shall be made of concrete, natural stone, iron or other equally durable material.)
Describe witness monuments.



- (d) Show a plan view drawing depicting the relevant monuments and reference ties which is sufficient in detail to enable accurate relocation of the corner monument if the corner monument is disturbed. Indicate north.



5-7

Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

None

- (f) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?
(2)

- (g & h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location.

COR. REESTABLISHED BY OWENS - ILLINOIS THROUGH SINGLE
PROPORTIONING



- (i) I, WILLIAM F. KELLY
(type or print name)

certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

William F. Kelly 8/27/90
Signature Date

