

CERTIFIED LAND CORNER RESTORATION


Index No. P-5

State of Wisconsin }  
County of Lanlade } ss.

I Raymond J. Hallisy, do hereby certify that on the 21st day of April, 19 79, I found evidence of the EAST 1/4 corner of 19 Township 33, North, Range 13 EAST, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:

.....  
.....  
.....



○ = Corner monument restored.

History of original corner establishment:


CORNER REESTABLISHED in 1928 BY M. HUTCHINSON  
County Surveyor

Description of corner evidence found:

1" Axle for corner  
4"x4" scribed cedar post 10" south of Axle  
old B.T.  
Pine stump 558W 11'3"

Description of monument and accessories I established to perpetuate the original location of this corner.

Set 2" IRON PIPE with Brass cap in place of Axle  
New B.T.s  
White pine 22" S75E 4'3"  
Hemlock 14" S41W 47'6"  
Hemlock 14" S45W 45'9"



Dated at Antigo, Wis., this 21st day of April, 19 79.

Signature Raymond J. Hallisy Title Reg. Land Surveyor Registration No. 5685  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of \_\_\_\_\_, I hereby certify that the within instrument was filed in this office for record on the \_\_\_\_\_ day of \_\_\_\_\_, 19 \_\_\_\_\_ at \_\_\_\_\_ o'clock \_\_\_\_\_ M.

.....  
(Register of Deeds)

By \_\_\_\_\_ Deputy