

CERTIFIED LAND CORNER RESTORATION

33-13

Index No. X-5

State of Wisconsin }  
County of LANGLADE } ss.

I RAYMOND J. HALLISY, do hereby  
certify that on the 3RD day  
of JULY, 1971, I found  
evidence of the WEST 1/4  
corner of SECTION 32  
Township 33N, North, Range  
13E, Fourth, Principal Meridian,  
as described hereon; and that from this evidence  
I established a new monument and accessories  
as described hereon to perpetuate the original  
location of this corner.

Resident witnesses:

.....  
.....  
.....

History of original corner establishment:

OWENS - ILLINOIS SURVEY

Description of corner evidence found:


SQUARED & SCRIBED WOOD POST  
SCRIBED 531, 532, 1/4  
1 1/4" IRON PIPE ALONGSIDE

Description of monument and accessories I established to perpetuate the original location of this corner.

SET 4" BRASS CAP IN CEMENT - ROCK MOUND

NEW BT'S  
HARD MAPLE 12" S74°W 4.7 LKS  
" " 13" N14°E 30.5 LKS

BT'S SCRIBED AT BASE



○ = Corner monument restored.

Dated at Antigo, Wis., this 3RD day of JULY, 1971.

Signature R. J. Hallisy Title Reg. LAND SURVEYOR Registration No. 685  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of \_\_\_\_\_, I hereby certify that the within  
instrument was filed in this office for record on the \_\_\_\_\_ day of \_\_\_\_\_, 19\_\_\_\_  
at \_\_\_\_\_ o'clock \_\_\_\_\_ M.

.....  
(Register of Deeds)  
By \_\_\_\_\_ Deputy

FORM 985 H. C. MILLER CO., MILWAUKEE