

CERTIFIED LAND CORNER RESTORATION

34-9

Index No. D-21

State of Wisconsin }  
County of LAUGHLAN } ss.


I RAYMOND J. HALLISY, do hereby certify that on the 13 day of MAY, 1969, I found evidence of the S 1/16 corner of SEC. 1 Township 34, North, Range 9E, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:  
GERALD WEIX  
JERRY KRYKA

History of original corner establishment:  
CORNER SET IN 1937 BY T.H. KILROE AND D.A. HINTZ  
COUNTY RESURVEY PROJECT

Description of corner evidence found:  
OLD SOURCE POST - TOP BROKE OFF - POINT IN GROUND  
SCRIBED S 1/16 - SEC 1 AND SEC 2  
NO B.T.S.

Description of monument and accessories I established to perpetuate the original location of this corner.  
SET 2 INCH IRON PIPE WITH BRASS CAP AND ROCK MOUND  
MARKED  
134N R 9E  
S | S  
2 | 1  
S 1/16  
BEARING TREES MARKED WITH "B.T."  
HARD MAPLE 11" N66°E 31 FT.  
YELLOW BIRCH 11" S18°E 32 FT



○ = Corner monument restored.

Dated at ANT 190, Wis., this 4 day of June, 1969.  
Signature Raymond J. Hallisy Title Reg. Land Surveyor Registration No. 5-685  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)  
Office of Register of Deeds, County of \_\_\_\_\_, I hereby certify that the within instrument was filed in this office for record on the \_\_\_\_\_ day of \_\_\_\_\_, 19\_\_\_\_ at \_\_\_\_\_ o'clock \_\_\_\_\_ M.

\_\_\_\_\_  
(Register of Deeds)  
By \_\_\_\_\_ Deputy

FORM 985 N. C. MILLER CO., MILWAUKEE