

CERTIFIED LAND CORNER RESTORATION

34-90  
K-1  
Index No. ....

State of Wisconsin }  
County of Langlade } ss.

I, Raymond J. Hallisy, do hereby certify that on the 29th day of August, 1970, I found evidence of the N 1/16 corner of Sections 13 & 18 Township 34, North, Range 9E & 10E, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

History of original corner establishment:

Corner set in the 1930 resurvey

Description of corner evidence found:

Found old stake standing in swamp.

Resident witnesses:

.....  
.....  
.....



Description of monument and accessories I established to perpetuate the original location of this corner.

Set 2" pipe with brass cap, rock mound.

New B.T.'s

10" Hemlock N88W 20 Ft. 8 Inches  
8" Cedar S6E 6 Ft. 9 Inches

B.T.'s faced at base of tree and scribed BT



○ = Corner monument restored.

Dated at Antigo, Wis, this 29th day of August, 19 70

Signature Raymond J. Hallisy Title Reg. Land Surveyor Registration No. S-685  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of \_\_\_\_\_, I hereby certify that the within instrument was filed in this office for record on the \_\_\_\_\_ day of \_\_\_\_\_, 19 \_\_\_\_\_ at \_\_\_\_\_ o'clock \_\_\_\_\_ M.

.....  
(Register of Deeds)

By \_\_\_\_\_ Deputy

FORM 685 W. C. MILLER CO. - MILWAUKEE