

CERTIFIED LAND CORNER RESTORATION

Index No. N-13

State of Wisconsin }  
County of LANGLADE } ss.

I, RAYMOND S. HALLISY, do hereby certify that on the 19TH day of JUNE, 1976, I found evidence of the Section corner of 15, 16, 21, 22 Township 34, North, Range 9E, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:

.....  
.....  
.....

History of original corner establishment:

CORNER SET IN THE 1930 RESURVEY


34.9

Description of corner evidence found:

4" PIPE WITH BRASS CAP  
OLD BT. 14" HEMLOCK S75W 67.12 LKS.  
NOW 22"

Description of monument and accessories I established to perpetuate the original location of this corner.

NEW BT'S  
10" BLACK ASH N7W 30.1 FT.  
8" RED MAPLE N78W 28.6 FT  
8" BLACK ASH S82E 34.3 FT



○ = Corner monument restored.

Dated at Antigo, Wis., this 19TH day of JUNE, 1976.

Signature Raymond S. Hallisy Title Reg. Land Surveyor Registration No. 5685  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of \_\_\_\_\_, I hereby certify that the within instrument was filed in this office for record on the \_\_\_\_\_ day of \_\_\_\_\_, 19\_\_\_\_ at \_\_\_\_\_ o'clock \_\_\_\_\_ M.

.....  
(Register of Deeds)

By \_\_\_\_\_ Deputy

4340916 0000 1976

FORM 985 H. C. MILLER CO., MILWAUKEE