

CERTIFIED LAND CORNER RESTORATION

History of original corner establishment:

CORNER RESURVEYED IN 1937 BY T. H. KILROE AND D. A. HINTZ

State of Wisconsin }
County of LANGLADE } ss.

I RAYMOND J. HALLISY, do hereby certify that on the 24 day of MAY, 1969, I found evidence of the W 1/6 corner of SEC 21 Township 34, North, Range 9 E, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:

JERRY KEYKA
GERALD WEIX

Description of corner evidence found:

4" SQUARED POST MARKED 1/8 5/16
5 21

OLD B.T WHITE PINE 12 548°W 44.24 LKS


Description of monument and accessories I established to perpetuate the original location of this corner.

2" IRON PIPE WITH BRASS CAP MARKED

T 34N R 9 E
W 1/6
5 16
5 21


BEARING TREES WITH SCRIBED "B.T." (X)

- 1) RED MAPLE 7" N 33° E 6' 3"
- 2) WHITE PINE 22" S 50° W 29' 0"
(SAME AS ABOVE)



4340916 0030 1969

FORM 985 M. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.

Dated at ANT 190, Wis., this 4th day of JUNE, 1969.

Signature Raymond J. Hallisy Title Reg. Land Surveyor Registration No. 5-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

(Register of Deeds)
By _____ Deputy