

CERTIFIED LAND CORNER RESTORATION

Index No. N-5

34-9

43409 18 0000 1977

FORM 985 M. C. MILLER CO., MILWAUKEE

State of Wisconsin }
County of Langlade } ss.

I Raymond J. Hallisy do hereby certify that on the 26th day of November, 1977, I found evidence of the Section corner of 17, 18, 19, & 20 Township 34, North, Range 9E, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:

.....
.....
.....

History of original corner establishment:

Corner set in the 1930 resurvey.


Description of corner evidence found:

4" iron pipe with brass cap. Highway "H" east.

Description of monument and accessories I established to perpetuate the original location of this corner.

New PT's to witness corner

- 4" White pine S62W 12' 8"
- 10" White Pine S38W 16' 9"
- 4" White Pine S12W 26' 7"



○ = Corner monument restored.

Dated at Antigo, Wis., this 26th day of November, 1977.

Signature Raymond J. Hallisy Title Land Surveyor Registration No. S685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

.....
(Register of Deeds)
By.....Deputy