

CERTIFIED LAND CORNER RESTORATION

Index No. R-9

State of Wisconsin }
County of Lannglade } ss.

History of original corner establishment:

34-9

CORNER SET IN THE 1930 RESURVEY

I Raymond S. Hallisy, do hereby certify that on the 26th day of JUNE, 1976, I found evidence of the Section corner of 20, 21, 28, 29 Township 34, North, Range 9E, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.



Description of corner evidence found:

4" PIPE WITH BRASS CAP
LOCATION POSTER 2 CHAINS SOUTH
ON OLD FIRE LANE.

Resident witnesses:

Description of monument and accessories I established to perpetuate the original location of this corner.

NEW BT'S
7" HARD MAPLE NSW 23.6 FT
8" YELLOW BIRCH S 74 E 19.4 FT
7" YELLOW BIRCH S 6 W 5.8 FT



○ = Corner monument restored.

Dated at Antigo, Wis., this 26th day of JUNE, 1976.

Signature Raymond S. Hallisy Title Reg Land Surveyor Registration No. 5685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy