

CERTIFIED LAND CORNER RESTORATION

34-10
Index No. B-13

State of Wisconsin }
County of Langlade } ss.

I, Raymond J. Hallisy, do hereby certify that on the 2nd day of May, 1970, I found evidence of the N 1/16 corner of Section 3 Township 34, North, Range 10E, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

History of original corner establishment:

Corner set in the 1930 resurvey.

Description of corner evidence found:

Found old stake standing in swamp, marked N1/16 3 4
Random line to east and south.

Resident witnesses:

J. Weis
J. Krupke

Description of monument and accessories I established to perpetuate the original location of this corner.

Set 2" pipe with brass cap.

New B.T.'s


Tamarack 9" N42W 5 Ft. 7 inches

Spruce 6" S42W 15 Ft. 4 inches

B.T.'s faced at base of tree and scribed BT.



FORM 985 H. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.

Dated at Antigo, Wis., this 2nd day of May, 1970

Signature Raymond J. Hallisy Title Reg. Land Surveyor Registration No. S-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy