


CERTIFIED LAND CORNER RESTORATION

Index No. G-7

State of Wisconsin }
County of LANGLADE } ss.

History of original corner establishment:



William F. Kelly



I WILLIAM F. KELLY, do hereby certify that on the 15TH day of JUNE, 1978, I found evidence of the CENTER corner of SECTION 8 Township 34, North, Range 10E, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Description of corner evidence found:
LOCATED EXISTING 2" I.P. IDENTIFIED ON SUBDIVISION PLAT AS CENTER OF SECTION 8, TAN, R10E.
FOUND OLD BEARING TREE.
MARKED NEW BEARING TREES.

Resident witnesses:

.....
.....
.....

Description of monument and accessories I established to perpetuate the original location of this corner.



Dated at ELCHO, Wis., this 9TH day of OCTOBER, 1978.

Signature William F. Kelly Title COUNTY SURVEYOR Registration No. S-1098
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19..... at..... o'clock..... M.

(Register of Deeds)

By..... Deputy

○ = Corner monument restored.

FORM 985 H. C. MILLER CO., MILWAUKEE