

CERTIFIED LAND CORNER RESTORATION

Index No. U-24

State of Wisconsin }
County of Langlade } ss.

History of original corner establishment:

Corner established in 1882 by B.F. Dorr, county surveyor.


I, Daniel K. Pleoger, do hereby certify that on the 10th day of November, 1980, I ~~found~~ ^{established} evidence of the SE 1/16 corner of Section 25 Township 35, North, Range 10 East, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Description of corner evidence found:

No evidence of old corner.

Corner established by subdivision of the SE 1/4. Location of SE 1/16 corner is S1-43-37W 1334.97 feet of EC 1/16 and N89-41-24E 1253.991 feet of SC 1/16.

Resident witnesses:



Description of monument and accessories I established to perpetuate the original location of this corner.


Set a 1-1/2" I.D. iron pipe with screw-on brass cap - stamped:
Projecting 12" above ground.

Marked NBT's:

Maple 6" N25°E 5.18 feet
Maple 7" S86°W 25.50 feet scribed 1/16 B.T.
Maple 5" S38°W 14.28 feet

T34N R10E
SE 1/16 S+25
S1537-1980

FORM 985 H. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.

Dated at Rhineland, Wis., this 25th day of February, 1981.

Signature Daniel K. Pleoger Title Registered Land Surveyor Registration No. 1537
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy