


CERTIFIED LAND CORNER RESTORATION

Index No. T-24


State of Wisconsin }  
County of Langlade } ss.

I Daniel K. Pleoger, do hereby certify that on the 10th day of November, 1980, I found evidence of the EC 1/16 corner of Section 25 Township 34 North, Range 10 East, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:



FORM 983 M. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.

History of original corner establishment:

Corner established in 1882 by B.F. Dorr, county surveyor, from which Hemlock 8" bears N89-1/2°E 17.5 links and Hemlock 7" bears S85°W 13.5 links.

Description of corner evidence found:

No evidence of old corner.  
Corner established by traverse and computation.  
Total distance from C 1/4 corner section 25 to 1/4 corner between sections 25 and 30 is 2492.441 at bearing S89-35-11E.  
Set EC 1/16 corner 1246.221 feet intermediate.

Description of monument and accessories I established to perpetuate the original location of this corner.

Set a 1-1/2" iron pipe with screw-on brass cap - stamped:  
Projecting 18" above ground.

Marked NBT's:-

Cedar 7" N63°E 17.35 feet  
Cedar 7" S49°E 8.72 feet scribed 1/16 B.T.  
Cedar 5" N71°W 16.80 feet  
T34N R10E  
EC 1/16 S+25  
S1537-1980

Dated at Rhinelander, Wis., this 25th day of February, 1981.

Signature Daniel K. Pleoger Title Registered Land Surveyor Registration No. 1537  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of \_\_\_\_\_, I hereby certify that the within instrument was filed in this office for record on the \_\_\_\_\_ day of \_\_\_\_\_, 19\_\_\_\_ at \_\_\_\_\_ o'clock \_\_\_\_\_ M.

(Register of Deeds)

By \_\_\_\_\_ Deputy