

CERTIFIED LAND CORNER RESTORATION

Index No. Y-17

State of Wisconsin }  
County of Langlade } ss.

I, Daniel K. Pleoger, do hereby certify that on the 26th day of August, 1980, I ~~re-established~~ established ~~at the~~ S 1/16 corner of section 34 Township 34, North, Range 10 East, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.


History of original corner establishment:

Recovered an old squared cedar post which bears due west 13.60 feet of new established corner.

Description of corner evidence found:

Ran traverse from section corner 34-35 - 34-10 to 1/4 corner between sections 34-35 for a distance of 3200.087 feet at bearing N1-17-05W. Set S 1/16 corner 1600.042 intermediate.

Resident witnesses:



Description of monument and accessories I established to perpetuate the original location of this corner.

Set a 1-1/2" I.D. iron pipe with screw-on brass cap, stamped:

Monument projects 18" above ground.

Marked NBT's -

Yellow Birch 5" N41°W 7.60 feet


Yellow Birch 7" S61°W 21.38 feet

Hemlock 10" S35°E 42.00 feet

all scribed 1/16 B.T.

T34N R10E  
S 1/16 34 + 35  
S1537-1980

FORM 983 H. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.

Dated at Rhineland, Wis., this 26th day of November, 1980

Signature Daniel K. Pleoger Title Registered Land Surveyor Registration No. S-1537  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of \_\_\_\_\_, I hereby certify that the within instrument was filed in this office for record on the \_\_\_\_\_ day of \_\_\_\_\_, 19\_\_\_\_ at \_\_\_\_\_ o'clock \_\_\_\_\_ M.

(Register of Deeds)

By \_\_\_\_\_ Deputy