U.S. PUBLIC LAND SURVEY MONUMENT RECORD (Prepared and as required by S. A-E 7.08 W Administrative Code)

The	NORTHWEST	corner of Section.	4 T	34 N B	10 E	Langlade County W	
	ner was: (check all	that apply)				conglede County, W	
		acceptance of an obliterated e acceptance of a found perpetu			0.51	000 0000	
	Determined to be	lost and re—established throug and distances to PLSS corners	gh proportion	ate methods.	351	032 0000	
	Restored/recovered	d/reestablished in a location t tion. (Show difference in plan	hat differs fr		sly		
	·	tional information is shown on	•	side of this	form.		
		ce, recovered physical evidence	, occupation	al evidence, t	estimoniai	evidence and all othe	r evidence
The	original corner wa	very/restoration of the corner. as established in 1859 by Hira	ım C. Fellov	s. Original b	earing tre	es: sugar, 7", N47°V	V, 6
link	s aspen, 9", N10°	E. 28 links; aspen, 14", S32°l	E, 23 links, a	and an aspen,	, 12", S51	°W, 17links. In 193	7, D.
A. I	lintz retraced the	original government survey a	nd found: "s	ection lines b	plazed N-1	S and E-W. Found p	art of
old	scribed stake and I	BT by unknown surveyor: he	mlock stump), 12", N82°' Jra (13-13'):	W, 35.1 lk hemlock	(S. Mage new B1 S) 10" N67°W 49.2 li	mapie, nks
18"	, N80-1/2°E, 44 lif 47') and a new R0	nks (29.04'); maple, 12", S27 D: cross on top of grey rock,	N01°E 25 6	.ks (13.13 <i>)</i> , 5 links (16.9°). In 1980	o. former surveyor K	Celly
"for	ind a 4" brass cap	monument set in concrete" a	nd marked 3	BT's. 10/13	3/98 D. T	'lusty, D. Williams.	Found
4" i	ron pipe with brass	s cap and all four 1937 bearing	ig objects. I	The found mo	onument lo	ocation doesn't work	t with
193	7 record ties. I re-	-set the monument using the	1937 ties.				
Phy	sical description of	the monument set:					
For	the corner, I re-se	t the 1937 monument, a 4" p	ipe with bra	ss cap, then r	measured	new ties as shown be	elow.
	·						
Des	cribe the accessorie	es used to perpetuate the loca	ation of the	corner Includ	ie a nian v	dew drawing and Indic	orte
acc	essories found/set. in future recovery	Describe measuring point on	bearing tree	s. Show any	topograph	nick that months are the months and the months are	ď
\mathcal{O}	= set aluminum nai	il (ν) in low blaze on side of	tree shown			FB 16-48	
ъ		1. 1 1					
	rings magnetic with	in nand compass S61°E, 11.9' from "found"	location. It	appears that	the monu	ment may have been	1
bull	dozed out at one t	ime (it is on the north edge of	f east-west	rail) and son	neone re-s	et it without using th	ie 19 3 7
ties	, and then Kelly di	dn't check the 1937 ties eithe	er, but used	the monumer	nt as found	i .	
		FOUND PKIN FACE OF					Å
	//	(KEILY BT)					(N)
	—		FND	CHISELED"X" (1937 BO)	"ON ROCK	:	
	\$ix		(F) 24 (F)	(1937 BO)			
	16"HEMLOCK (1937 BT)	163. W S. E	· (b/.		22"M	APLE 1787)	•
	(1121 21)	.26.	7/20 2/00	N84°E	_EJ (743	767)	
	ONEIDA	COUNTY	<u> </u>	29.25		T35N	
	LANGLADE	COUNTY	TRAI	·4 ¬	~	7 34 N	
				£			
		3/10 2/0	100	CORNER, 4	1.24.10		
				4"IP W/BRA			
		IS MAPLE	FROM	n 1937 TIES			
		(M37 BT)				The NORTHWEST	_
			SU	RVEYORS SEA		corner of Section <u>4</u>	
			ent	Marie C. D. A.		T. <u>34</u> N., R. <u>/0</u> E Langlade County, W	
	_		Arterity (1200000000	PA III	•	INDEX No
زا	DAVID E. TLUSTY LANGUADE COUNT	<u> Υ <i>Sunviyon</i></u> , certify that the	i a	DAVID E.°			è.
cor	ner location shown	on this record was determined rection and control and that t	his man	S-1390			.
U.S	. Public Land Surve	y Monument Record is correct	19:	ANTIGO	2		7
unc		pest of my knowledge and belie		80000000000000000000000000000000000000	A LIGHT		7 7
	1701	(1 + 1 - 1-1-	S. C.	OLAND S	Marithia.		0/20
Sin	nature	1 mily 6/15/99	<u>1</u>	-460803003788313FCZg.		O=Location of corne	er
uigi		, Dule					

WISCONSIN ADMINISTRATIVE CODE

A-E 7.07 Monuments. The type and position of monuments to be set on any survey shall be determined by the nature of the survey, the permanency required, the nature of the terrain, the cadastral features involved, and the availability of material. History: Cr. Register, February, 1987, No. 374, eff. 3-1-87.

A-E 7.08 U.S. public land survey monument record.

- (1) WHEN MONUMENT RECORD REQUIRED. A U.S. public land survey monument shall be prepared and filed with the county surveyor's office as part of any land survey which includes or requires the perpetuation, restoration, reestablishment or use of a U.S. public land survey corner, and,
- (a) There is no U.S. public land survey monument record for the corner on file in the office of the county surveyor or the register of deeds for the county in which the corner is located; or,
- (b) The land surveyor who performs the survey accepts a location for the U.S. public land survey corner which differs from that shown on a U.S. public land survey monument record filed in the office of the county surveyor or register of deeds for the county in which the corner is located, or,
- (c) The witness ties or U.S. public land survey monument referenced in an existing U.S. public land survey monument record have been destroyed or disturbed.
- (2) FORM REQUIRED. A U.S. public land survey monument record shall be prepared on the board-approved form or on a form substantially the same as the board-approved form which includes all the elements required by this section. A form used for this purpose shall be entitled, "U.S. Public Land Survey Monument Record".

Note: A copy of the board-approved form is available from the Departed and of Regulation and Licensing, Bureau of Business and Design Professions, 1400 East Washington Avenue, P.O. Box 8935, Madison, Wisconsin 53708

- (3) MONUMENT RECORD REQUIREMENTS. A U.S. public land survey monument record shall show the location of the corner and shall include all of the following elements:
- (a) The identity of the corner, as referenced to the U.S. public land survey system;
- (b) A description of any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence considered by the surveyor, and whether the monument was found or placed;
- (c) Reference Les to at least 4 witness monuments. Witness monuments shall be concrete, natural stone, iron, bearing trees or other equally durable material, except wood other than bearing trees;
- (d) A plan view drawing depicting the relevant monuments and reference uses which is sufficient in detail to enable accurate relocation of the corner monument if the corner monument is disturbed;
- (e) A description of any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished;
- (f) Whether the corner was restored through acceptance of an obliterated evidence location or a found perpetuated location;
- (g) Whether the corner was reestablished through los*-corner-proportionate methods;
- (h) The directions and distances to other public land survey corners which were used as evidence or used for proportioning in determining the corner location; and,
- (i) The stamp and signature or seal and signature of the land surveyor under whose direction and control the corner location was determined and a statement certifying that the U.S. public land survey monument record is correct and complete to the best of his or her knowledge and belief.

History: Cr Register, February, 1987, No 374, eff. 3-1-87, mr (1) mu (1) (c), Register, May, 1989, No 401, eff. 6-1-89

COPY TO ONGOA CO. 12/10/99 2.T.

O = Corner monument restored.

State of Wisconsin

I WILLIAM F. KELLY, do hereby certify that on the 26th day of DECEMBER, 19.80, I found evidence of the NE corner of Sec. 5

Township 34, North, Range 10 €, Fourth Principal Meridian, as described hereon; and that from this evidence

I established a new monument and accessories

as described hereon to perpetuate the original

County of LANGLADE

location of this corner.

Resident witnesses:

COTICION	LANID	CODMICO	RESTORATION	A I
, F D 1 1 F 1 F 1 J	IANII	CODINED	DECTORATION	N
,_ (\ 11 11 1		CONTRACT	NESTONATION	

Index No. A - 9


History of original corner establishment:

DRIGINAL CORNER ESTABLISHED BY JAMES NOWLIN IN 1865.

Description of corner evidence found:

FOUND A 4" BRASS CAP MONUMENT

SET IN CONCRETE



Description of monument and accessories I established to perpetuate the original location of this corner.

- 18" HEM LOCK

NORTH	BT's	18" HEMLOCK	SET IN	SS CAP MON. CONCRETE IN PLACE	T35N, R 32 + 33 5 + 4 T34 N 12 - 3-	
Dated at	Есно	, Wis., this	26 6h	day of DEC	2	, 19.80
Signature	William o	Title		SURUEYOR authorized official)	Registration N	10. 1098
066 610	· (D			•	haralist contifer the	at tha withir

(Register of Deeds)

By.....Deputy