

CERTIFIED LAND CORNER RESTORATION

34-10
Index No. A-20

State of Wisconsin }
County of Langlade } ss.

History of original corner establishment:

I Raymond J. Hallisy, do hereby certify that on the 8th day of June, 19 68, I found evidence of the E 1/16 corner of Section 2 Township 34, North, Range 10, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Corner set in the 1930's by: C. W. Borth
E. F. Kowalke
D. A. Hintz

Description of corner evidence found:

**Found squared stake, rock mound.
marked E 1/16 S2 S35**


Resident witnesses:

.....
.....
.....


Description of monument and accessories I established to perpetuate the original location of this corner.

Set Std. 1 1/2" pipe with cap marked E 1/16 2 35

FORM 985 N. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.



Dated at Antigo, Wis., this 8th day of June, 19 68.

Signature Raymond J. Hallisy Title Reg. Land Surveyor Registration No. A-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19 _____ at _____ o'clock _____ M.

.....
(Register of Deeds)

By _____ Deputy