

Section 29, Township 32 North, Range 9 East



#	N	E	Desc
323	374978.30	555311.26	sec cor from ties gh spk set
69	374631.32	557896.41	1/4 best fit from kelly ties mag
406	374314.20	560480.42	RTK SEC COR GH SPK FND
50	371645.93	560442.22	static fixed E1/4x S29 2\"/>

Langlade County Coordinates NAD83(2011) datum

NO.	DATE	DESCRIPTION	BY


David E. Tlusty, Langlade County Surveyor
 837 Clermont Street (715)627-6311 Antigo, WI 54409

LANGLADE COUNTY

LAND RECORDS & REGULATIONS DEPARTMENT

SCALE:	1" = 400'
DRAWN BY:	D. TLUSTY
REF. FILE:	FB 23
DATE:	03/23/2017
TOWN OF:	VILAS
TOWN CODE:	
cogo file:	343209
LOCATION:	
SECTION:	29
TOWNSHIP:	32
RANGE:	09
DWG. #:	
..SURVEYS/T32N/293209	

I, David E. Tlusty, Langlade County Surveyor, do hereby certify that by the direction of the Langlade County Forestry Department, I have made a survey of part of Section 29, Township 32 North, Range 9 East, as shown hereon. I further certify that this map is a true and correct representation of said survey and that this survey is correct to the best of my knowledge and belief.

April 20, 2017 
 David E. Tlusty, S-1390
 Langlade County Surveyor

RECORD # 30058
 LANGLADE COUNTY SURVEYORS OFFICE
 DATE FILED: 4/21/2017 BY: D. Tlusty

LEGEND
 ○ = 1" x 30" iron pipe set
 ⊙ = 3/4" x 30" rebar set
 — boundary flagged and painted blue

Note for SW 1/16th corner. 3/21/2017
 D. Tlusty, C. Brauner set this corner based on the section corner information shown. We found an existing 1 1/4" iron pipe, S 21°51' E, 67.0' and also found a pattern of three old bearing trees to the NE which would indicate a corner was thought to be about N 35° E, 20' from the rebar we set. No survey maps exist in the County Surveyor records for this section.

South 1/4 Corner, Section 29
 Set 1" x 36" iron pipe by single proportionate measure.

Southeast Corner, Section 29
 Set 2" x 30" iron pipe by double proportionate measure.