



Found 1 1/2" iron pipe with brass cap, set by Ray Hallisy in 1973, to replace a well point that he found, along with a squared stake (scribed) and an angle iron. Hutchinson used this corner in 1916. It was common for Hutchinson to use well points.

Malcolm Hutchinson used this corner in 1916 to set a corner north of here. He found the stump of an orig. B.T. with marks and made 2 new bearing trees. Searched extensively at Hutchinsons distance from the north. Found nothing. Corner re-established by single proportionate measurement. Set a 2" x 30" iron pipe with brass cap for the corner.

Found 2" iron pipe with brass cap, set by Ray Hallisy in 1970 to replace an old squared stake with rock mound that he found.

There is no evidence in the records that this corner was ever used or maintained after the original government survey. Corner re-established by single proportionate measurement. Set a 2" x 30" iron pipe with brass cap for the corner. Corner falls in the north rut of a good logging road.

There is no evidence in the records that this corner was ever used or maintained after the original government survey. The corner was considered lost and re-established by double proportionate measurement. Set a 1" x 30" iron pipe with 2" aluminum cap for corner. Corner falls in logging road. See new corner restoration form.

Found a 3/4" iron pipe in road as per Kelly, 05/08/90. Kelly set this pipe over an iron pipe found, down 12", which is possibly a pipe set by Hutchinson in 1916.

Found aluminum capped monument set by Kelly, in 1990, to replace 1 1/4" iron pipe and scribed 4" x 4" wood post he found as "cor. perpetuated by Owens-Illinois in 1977". A 1977 map of Section 17 by Bill Stuth depicts this corner as a corner "By others".

Langlade County Coordinate system values for corners in the area of Section 5, T32N, R13E

| # | N | E | DESCRIPTION |
|-----|------------|------------|---------------------------------|
| 27 | 395512.696 | 689163.743 | IP W/BCAP NW COR 4-32-13 |
| 84 | 390025.985 | 683988.998 | 1 1/2" IP W/BCAP SW COR 5-32-13 |
| 209 | 382131.621 | 689201.713 | 2" ALUM MON FND E 1/4 17-32-13 |
| 309 | 390031.365 | 702344.385 | RTK ON IP FND S 1/4 2-32-13 |
| 400 | 390022.181 | 689223.098 | IP SET SE COR 5-32-13 BY DPM |
| 401 | 390024.083 | 686606.048 | IP SET S 1/4 5-32-13 BY SPM |
| 402 | 392652.368 | 689194.664 | IP SET E 1/4 5-32-13 BY SPM |

I, David E. Tlusty, Langlade County Surveyor, do hereby certify that I have made a survey to re-establish the Southeast corner of Section 5, T. 32 N., R. 13 E., as shown hereon. I further certify that this map is a true and correct representation of said survey and that this survey is correct to the best of my knowledge and belief. Corner restoration forms are on file for all monumented corners shown.

June 3, 2004
 David E. Tlusty, S-1390
 Langlade County Surveyor

RECORD # 30543
 LANGLADE COUNTY SURVEYORS OFFICE
 DATE FILED: 6/10/04 BY: D. Tlusty

| | |
|---|-----------------------|
| THIS DOCUMENT WAS CREATED ON LANGLADE COUNTY COMPUTER EQUIPMENT THAT WAS PURCHASED WITH THE ASSISTANCE OF A GRANT RECEIVED FROM THE WISCONSIN LAND INFORMATION BOARD. | |
| LANGLADE COUNTY LAND RECORDS & REGULATIONS DEPARTMENT | |
| SCALE: | 1" = 800' |
| DRAWN BY: | D. TLUSTY |
| REF. FILE: | FB 14 |
| DATE: | 06/03/04 |
| TOWN OF: | LANGLADE |
| TOWN CODE: | |
| LOCATION: | |
| SECTION: | 5 |
| TOWNSHIP: | 32 |
| RANGE: | 13 |
| DWG. #: | ..SURVEYS/T32N/053213 |
| No. | Date |
| REVISIONS | |
| By: | |