



Corner restorations forms are on file in the County Surveyors office for all section corners and quarter corners shown on this map. True bearings shown based on solar observation near the north quarter corner. This map is a compilation of existing survey information and not based on recent survey work by the Langlade County Surveyors Office.

NO.	DATE	DESCRIPTION	BY
THIS DOCUMENT WAS CREATED ON LANGLADE COUNTY COMPUTER EQUIPMENT THAT WAS PURCHASED WITH THE ASSISTANCE OF A GRANT RECEIVED FROM THE WISCONSIN LAND INFORMATION BOARD.			
<b>LANGLADE COUNTY</b> <b>LAND RECORDS &amp; REGULATIONS DEPT.</b>			
TITLE: COMPILATION OF SURVEY INFORMATION IN SECTION 18, T. 31 N., R. 14 E. NOTE: BECAUSE THIS INFORMATION IS FROM SEVERAL DIFFERENT SOURCES, AND IT HAS BEEN COMBINED WITH VERY LITTLE FIELD CHECKING, IT SHOULD BE USED WITH CAUTION.			
REF. FILE:	SCALE: 1" = 300'		
DRWN BY: dt	DATE: 09/09/93		
	DWG. #: 183114r1		

RECORD # 42307  
LANGLADE COUNTY SURVEYORS OFFICE  
DATE FILED: 9-3-99 BY: AKM